



**REPAIR DEPARTMENT ESTIMATE**  
**1334 S. MERIDIAN ST, INDIANAPOLIS, IN 46225**

PH: (317) - 231-8080 FAX: (317) - 683-2095



**CUSTOMER**

WHITESTOWN UTILITY  
7728 CO. RD. 450E  
BROWNSBURG, IN 46112

ATTN: RICK

**QUOTE INFO**

QUOTE # V8734  
QUOTE BY WALTER BOAT  
EMAIL wboat@brehob.com  
TERRITORY BRIAN JOHNSON  
DATE 8/17/2023  
VALID 30 DAYS

**DESCRIPTION**

TECO 20HP, 875RPM, 324LPZ FRAME, MIXER MOTOR W/ IMPELLER  
M/N: AEUE8R  
S/N: NY7131018005B04129D

**FINDINGS**

SHAFT LOCKED UP UPON RECEIPT - COULD NOT TEST  
RUN - AFTER INSPECTION FOUND BEARING SIEZED  
AND MECHANICAL FITS BAD

**WORK SCOPE**

- DISMANTLE MOTOR
- CLEAN COMPONENTS PARTS
- PERFORM MECH/ELECT INSPECTION
- REPAIR DRIVE END HOUSING
- REPAIR OPP DRIVE END HSG
- REPAIR SEAL FIT
- MFGR NEW SLINGER BUSHING
- FURNISH AND INSTALL NEW BEARINGS
- FURNISH AND INSTALL NEW SEAL
- ASSEMBLE UNIT AND TEST
- PAINT AND PREP FOR SHIPMENT

**NOTES**

\*CUSTOMER PROVIDED NEW IMPELLER



**PRICING**

REPAIR ESTIMATE: \$5,954.00 PLUS FREIGHT

\*Lead Time: 3-4 WEEKS

INSPECTION FEE IF NOT REPAIRED/REPLACED: \$395.00

TERMS: NET 30 DAYS (WITH APPROVED CREDIT)

Customer P.O. : \_\_\_\_\_

Signature: \_\_\_\_\_

Please sign & return via email or fax this sheet when authorizing the work covered in this quote



**REPAIR DEPARTMENT ESTIMATE**  
**1334 S. MERIDIAN ST, INDIANAPOLIS, IN 46225**

PH: (317) - 231-8080 FAX: (317) - 683-2095



**CUSTOMER**

WHITESTOWN UTILITY  
7728 CO. RD. 450E  
BROWNSBURG, IN 46112

ATTN: RICK

**QUOTE INFO**

QUOTE # V8735  
QUOTE BY WALTER BOAT  
EMAIL wboat@brehob.com  
TERRITORY BRIAN JOHNSON  
DATE 8/17/2023  
VALID 30 DAYS

**DESCRIPTION**

WEG 125HP, 1780RPM 444/5T FRAME, TEFC  
M/N: PES.191957-1-A  
S/N: RARZ-183115000

**FINDINGS**

BEARINGS ARE WORN AND GREASE IS CONTAMINATED ON BOTH PIECES (ROLLER BEARING IN DRIVE END / INSULATED BEARING OPP DRIVE END)

**WORK SCOPE**

- DISMANTLE MOTOR
- CLEAN COMPONENTS PARTS
- PERFORM MECH/ELECT INSPECTION
- DYNAMICALLY BALANCE ROTATING ELEMENTS
- FURNISH AND INSTALL NEW BEARINGS
- FURNISH AND INSTALL NEW AEGIS RING
- ASSEMBLE UNIT AND TEST AT NO-LOAD
- PAINT AND PREP FOR SHIPMENT

**NOTES**

\*MOTOR HAS AN AEGIS GROUNDING RING ON DRIVE END AND INSULATED BEARING ON OPPOSITE DRIVE END. NO INDICATIONS OF FLUTING ON UNIT



**PRICING**

REPAIR ESTIMATE: \$4,974.00 PLUS FREIGHT

\*Lead Time: 3-4 WEEKS

INSPECTION FEE IF NOT REPAIRED/REPLACED: \$395.00

TERMS: NET 30 DAYS (WITH APPROVED CREDIT)

Customer P.O. : \_\_\_\_\_

Signature: \_\_\_\_\_

Please sign & return via email or fax this sheet when authorizing the work covered in this quote



**REPAIR DEPARTMENT ESTIMATE**  
**1334 S. MERIDIAN ST, INDIANAPOLIS, IN 46225**

PH: (317) - 231-8080 FAX: (317) - 683-2095



**CUSTOMER**

WHITESTOWN UTILITY  
7728 CO. RD. 450E  
BROWNSBURG, IN 46112

ATTN: RICK

**QUOTE INFO**

QUOTE # V8765  
QUOTE BY WALTER BOAT  
EMAIL wboat@brehob.com  
TERRITORY BRIAN JOHNSON  
DATE 8/17/2023  
VALID 30 DAYS

**DESCRIPTION**

TECO 20HP, 875RPM, 324LPZ FRAME, MIXER MOTOR W/ IMPELLER  
M/N: 54H2010  
S/N: NY7131018005B04129D

**FINDINGS**

UNIT SPUN FREELY UPON RECEIPT -- AFTER DISMANTLING NOTED SIGNS OF FRETTING IN BOTH BEARING HOUSINGS

**WORK SCOPE**

- DISMANTLE MOTOR
- CLEAN COMPONENTS PARTS
- PERFORM MECH/ELECT INSPECTION
- REPAIR DRIVE END HOUSING
- REPAIR OPP DRIVE END HSG
- MFGR NEW SLINGER BUSHING
- FURNISH AND INSTALL NEW BEARINGS
- FURNISH AND INSTALL NEW SEALS
- ASSEMBLE UNIT AND TEST
- PAINT AND PREP FOR SHIPMENT
- 

**NOTES**

\*UNIT RECEIVED WITH IMPELLER



**PRICING**

REPAIR ESTIMATE: \$5,419.00 PLUS FREIGHT

\*Lead Time: 3-4 WEEKS

INSPECTION FEE IF NOT REPAIRED/REPLACED: \$395.00

TERMS: NET 30 DAYS (WITH APPROVED CREDIT)

Customer P.O. : \_\_\_\_\_

Signature: \_\_\_\_\_

Please sign & return via email or fax this sheet when authorizing the work covered in this quote